Minebea

■ Reference Characteristics

Motor Size	SM8 — F20
Number of Steps per Rotation	20 (18° / Step)
Drive Method	2 — 2 PHASE
Drive Circuit	BIPOLAR CONST. VOLT.
Drive Voltage	5 [V]
Current / Phase	
Coil Resistance / Phase	21 [Ω]
Drive IC	LB1836M
Magnet Material	Nd-Fe-B bonded magnet (N51)
Insulation Resistance	1M [Ω] MIN
Dielectric Strength	AC 100 [V] 1 [min]
Class of Insulation	CLASS E
Operating Temp.	- 10 [℃] ~ 50 [℃]
Storage Temp.	- 25 [°C] ~ 60 [°C]
Operating Hum.	5 [%] RH ~ 85 [%] RH


 $[\]divideontimes$ Bipolar only. Unipolar is not available.



OA Equipment : Network cameras


Optical instrument: Digital cameras / Microscope

■ Torque Characteristics



These torque values are reference only. Heat radiation conditions and temperature rise effect by duty are different on each equipment, therefore please select motors after considering the actual equipment.

Dimensions



Please contact our sales for inventory and lot information. Specification may be changed without notice.



^{*}No dew condensation.






Reference Characteristics

Motor Size	SMSH8 — F20
Number of Steps per Rotation	20 (18° / Step)
Drive Method	2 — 2 PHASE
Drive Circuit	BIPOLAR CONST. VOLT.
Drive Voltage	5 [V]
Current / Phase	
Coil Resistance / Phase	21 [Ω]
Drive IC	LB1836M
Magnet Material	Nd-Fe-B bonded magnet (N51)
Insulation Resistance	1M [Ω] MIN
Dielectric Strength	AC 100 [V] 1 [min]
Class of Insulation	CLASS E
Operating Temp.	- 10 [°C] ~ 50 [°C]
Storage Temp.	- 25 [°C] ~ 60 [°C]
Operating Hum.	5 [%] RH ~ 85 [%] RH




^{*}No dew condensation.



OA Equipment : Network cameras


Optical instrument: Digital cameras / Microscope

■ Torque Characteristics



These torque values are reference only. Heat radiation conditions and temperature rise effect by duty are different on each equipment, therefore please select motors after considering the actual equipment.

Dimensions



Please contact our sales for inventory and lot information. Specification may be changed without notice.

Minebea




■ Reference Characteristics

Motor Size	SMSH8 — F40
Number of Steps per Rotation	40 (9° / Step)
Drive Method	2 — 2 PHASE
Drive Circuit	BIPOLAR CONST. VOLT.
Drive Voltage	5 [V]
Current / Phase	
Coil Resistance / Phase	21 [Ω]
Drive IC	LB1836M
Magnet Material	Nd-Fe-B bonded magnet (N51)
Insulation Resistance	1M [Ω] MIN
Dielectric Strength	AC 100 [V] 1 [min]
Class of Insulation	CLASS E
Operating Temp.	- 10 [°C] ~ 50 [°C]
Storage Temp.	- 25 [°C] ~ 60 [°C]
Operating Hum.	5 [%] RH ~ 85 [%] RH




≫No dew condensation.



OA Equipment : Network cameras


Optical instrument: Digital cameras / Microscope

Torque Characteristics



These torque values are reference only. Heat radiation conditions and temperature rise effect by duty are different on each equipment, therefore please select motors after considering the actual equipment.

Dimensions



Please contact our sales for inventory and lot information. Specification may be changed without notice.

